

Posi-Lok™ Plugs and Panels

PARTS, TOOLS AND ACCESSORIES

PART NUMBER	DESCRIPTION
A400001	E0315 and E0400 Assembly Tool.
A100632	Tool for removing E0315 and E0400 contacts from insulators.
A100072	Cable Cutter - #2 - 4/0 Cable.
201310	Insulator holding bracket.
A201303	Assembly tool for 200A plugs.
A200020-3	COM-A-LONG for pulling male contact in E0315 and E0400 Series.
A200020-4	COM-A-LONG for pulling female contact in E0315 and E0400 Series.
A101208	2 oz. tube silicon grease for lubricating mating end of synthetic rubber insulators.

REPLACEMENT PARTS

CONNECTOR SERIES NO.	SET SCREW	COPPER SHIM	PRESSURE PAD	RETAINING WIRE
E0200	100012-33	100400-5		100573-1
E0315	100012-18	100400-5	101214	100573-1
E0400	100012-18	100400-8	101214	100573-1

PROTECTIVE PLUG CAPS

PART NO.	DESCRIPTION
A100601-17	Cap for male E0315 or E0400
A100602-17	Cap for female E0315 or E0400
A201319-1	Cap for male E0200
A201319-1	Cap for female E0200

E0315 AND E0400 SERIES CRIMPING NEST AND PRESSES*

CABLE SIZE	CRIMPING NESTS PART NO.	CRIMPING PRESSES (INCLUDES CRIMP NEST)
#2-#1	100514-3	A200914-3
1/0-2/0	100514-4	A200914-4
3/0	100514-5	A200914-5
4/0	100514-6	A200914-6



*REFER TO INSTRUCTION SHEETS FOR E0200 CRIMPING INFORMATION